



1. Thickness measurement of a bimetal band

The thickness of a bimetal band should be controlled. For this purpose a pair of laser displacement sensors (master/slave – sensors) type **L-LAS-LT-37-MA** and **L-LAS-LT37-SL** mounted on a metal plate type **C-MOUNT-LT-37** is used. The bimetal band is guided centric. The thickness can be proper measured as shown in the screen shots.

