



### 1. Cutoff point detection of nonmetallic strapping

The cutoff point of nonmetallic strapping should be detected. For this purpose a color sensor type **SPECTRO-3-30-POL** is used. At this, the distance of the sensor to the plastic band is approximately 20mm. The cutoff point can be proper detected as shown in the screen shots.

